

Firmware Historie / History TR1200IP

updated: 2016-06-06 / Fu

Inhaltsverzeichnis / Table of contents

1 Firmware Historie (Deutsch)	1
Hinweis GOOSE:.....	1
Firmware 12390-1400-10 (2016-06-06)	1
Firmware 12390-1400-09 (2016-01-15)	1
Firmware 12390-1400-08 ()	1
Firmware 12390-1400-07 (2014-03-11)	1
Firmware 12390-1400-06 (2010-08-11)	1
2 Firmware history (english)	2
Hint GOOSE:.....	2
Firmware 12390-1400-10 (2016-06-06)	2
Firmware 12390-1400-09 (2016-01-15)	2
Firmware 12390-1400-08 ()	2
Firmware 12390-1400-07 (2014-03-11)	2
Firmware 12390-1400-06 (2010-08-11)	2

1 Firmware Historie (Deutsch)

Hinweis GOOSE:

Bei Geräten mit Auslieferungsfirmware <= 12390-1400-08 kann GOOSE nicht aktiviert werden, auch wenn ein Firmwareupdate auf >= 12390-1400-09 durchgeführt wird. (Aus lizenzrechtlichen Gründen).

Firmware 12390-1400-10 (2016-06-06)

Fehlerbeseitigung:

GOOSE lässt sich im Browser nicht aktivieren.

Firmware 12390-1400-09 (2016-01-15)

Neue Funktion:

GOOSE Protokoll (Nur bei Neugeräten verfügbar)

Firmware 12390-1400-08 ()

Interne Version.

Firmware 12390-1400-07 (2014-03-11)

Fehlerbeseitigung:

Relaiszustand wurde bei Relaiskonfiguration über Web falsch angezeigt.

Firmware 12390-1400-06 (2010-08-11)

Erste Freigabe.

2 Firmware history (english)

Hint GOOSE:

For devices with delivery firmware \leq 12390-1400-08, GOOSE cannot be activated, even if a firmware update is performed to \geq 12390-1400-09. (For reasons of copyright law)

Firmware 12390-1400-10 (2016-06-06)

Fehlerbeseitigung:

GOOSE cannot be activated in the browser.

Firmware 12390-1400-09 (2016-01-15)

Neue Funktion:

GOOSE Protocoll (Only available for new devices)

Firmware 12390-1400-08 ()

Internal version.

Firmware 12390-1400-07 (2014-03-11)

Fehlerbeseitigung:

Relay status was displayed incorrectly on relay configuration via Web.

Firmware 12390-1400-06 (2010-08-11)

First release.